

HAMSTIR Series Improvement Information of RF Interference

* Some malfunction may happen such as COM unstable or sound device lost.

Some PC made strong EMC/EMI countermeasure into it's USB circuits.

Also, HAMSTIR interface did similar countermeasure.

After that, both countermeasures made weak situation.

As this countermeasure is for receiving noise improvement of some other electrical products, for HAMSTIR basic functions, it's no affection.

At present, This was all applied into HAMSTIR DX andST by change of component from ferrite bead to jumper wire.

